



**NOMENCLATURE CHART
WITH SAFETY
SUGGESTIONS
FOR THE.....**

Band Saw



ROCKWELL DELTA 14" BAND SAW

SAFETY SUGGESTIONS


1. OBTAIN INSTRUCTOR'S PERMISSION TO OPERATE MACHINE.
2. REMOVE TIE, RINGS, WATCH AND ROLL UP SLEEVES.
3. WEAR GOGGLES OR A FACE SHIELD.
4. MAKE ALL ADJUSTMENTS WITH THE POWER OFF.
5. ADJUST THE UPPER GUIDE ABOUT 1/8" ABOVE THE MATERIAL BEING CUT.
6. PLAN YOUR CUTS, LAYOUT AND MAKE "RELEASE" CUTS BEFORE CUTTING LONG CURVES.
7. TURN OFF THE MACHINE BEFORE THE BLADE IS BACKED OUT OF THE CUT.
8. SHUT OFF THE POWER AND DO NOT LEAVE UNTIL THE MACHINE HAS COME TO A COMPLETE STOP.

Serving Industry
and Schools
for a Better America

Power Tool Division
Rockwell International

**NOMENCLATURE CHART
WITH SAFETY
SUGGESTIONS
FOR THE.....**

Drill Press



ROCKWELL DELTA 15" DRILL PRESS

SAFETY SUGGESTIONS

1. OBTAIN INSTRUCTOR'S PERMISSION TO OPERATE MACHINE.
2. REMOVE TIE, RINGS, WATCH AND ROLL UP SLEEVES.
3. HOLD THE MATERIAL SECURELY WITH A VISE OR CLAMPS.
4. WEAR GOGGLES OR A FACE SHIELD.
5. MAKE ALL ADJUSTMENTS WITH THE POWER OFF.
6. ADJUST THE TABLE AND DRILL TO AVOID DRILLING INTO THE TABLE.
7. CHECK THE LOCATION OF THE CHUCK KEY BEFORE TURNING ON POWER.
8. SHUT OFF THE POWER AND CLEAN TABLE BEFORE YOU LEAVE THE MACHINE.

20" DRILL PRESS


Serving Industry
and Schools
for a Better America



Power Tool Division
Rockwell International

**NOMENCLATURE CHART
WITH SAFETY
SUGGESTIONS
FOR THE.....**

Finishing Machines





Serving Industry
and Schools
for a Better America


Power Tool Division
Rockwell International

**NOMENCLATURE CHART
WITH SAFETY
SUGGESTIONS
FOR THE.....**

Scroll Saw



GUIDE ASSEMBLY



**LOWER PLUNGER
& TABLE ASSEMBLY**

ROCKWELL DELTA 24" SCROLL SAW

SAFETY SUGGESTIONS

1. OBTAIN INSTRUCTOR'S PERMISSION TO OPERATE MACHINE.
2. REMOVE TIE, RINGS, WATCH AND ROLL UP SLEEVES.
3. WEAR GOGGLES OR A FACE SHIELD.
4. MAKE ALL ADJUSTMENTS WITH THE POWER OFF.
5. LOWER THE HOLD DOWN TO PRESS LIGHTLY ON THE MATERIAL BEING CUT.
6. ROTATE THE MOTOR BY HAND TO CHECK ALL ADJUSTMENTS BEFORE TURNING POWER ON.
7. SHUT OFF POWER AND CLEAN MACHINE BEFORE YOU LEAVE IT.




Serving Industry
and Schools
for a Better America



Power Tool Division
Rockwell International

**NOMENCLATURE CHART
WITH SAFETY
SUGGESTIONS
FOR THE.....**

Wood Lathe



ROCKWELL DELTA 12" HEAVY DUTY VARIABLE SPEED WOOD LATHE **SAFETY SUGGESTIONS**

1. OBTAIN INSTRUCTOR'S PERMISSION TO OPERATE MACHINE.
2. REMOVE TIE, RINGS, WATCH AND ROLL UP SLEEVES.
3. MAKE ALL ADJUSTMENTS WITH THE POWER OFF.
4. WEAR GOGGLES OR A FACE SHIELD.
5. EXAMINE SET-UP CAREFULLY BEFORE TURNING ON POWER.
6. ALWAYS OPERATE MACHINE AT THE PRESCRIBED SPEEDS.
7. MAKE SURE THE TOOL REST IS ADJUSTED PROPERLY.
8. REMOVE THE TOOL REST BEFORE SANDING OR POLISHING.
9. SHUT OFF POWER AND CLEAN THE LATHE AFTER USING.

Serving Industry
and Schools
for a Better America

